

GENWAL COAL COMPANY

March 14, 1993

RECEIVED

MAR 14 1993

Mr. Daron Haddock
Division of Oil, Gas & Mining
3 Triad Center, Suite 350
355 West North Temple
Salt Lake City, UT 84180-1203

DIVISION OF
OIL GAS & MINING

RE: Permit # ACT 015-032
Genwal Coal Company
Division Order 92A

Dear Mr. Haddock:

Enclosed please find twelve (12) each of new plates, numbers 6-3 (isopach map or the Hiawatha coal seam), 6-4 (isopach map of the Blind Canyon coal seam), 6-5 (an isopach map of the Bear Canyon coal seam), and 6-6 (an overburden map of the Hiawatha coal seam, the only minable seam within the permit boundaries). These plate numbers will correspond with the renewal submittal of the mine and reclamation plan after the deficiencies, from the review completed by DOGM and addressed in a letter from you dated April 5, 1993, have been addressed by Genwal Coal Company.

Should you have any questions or need additional information, please feel free to contact me at 687-9813.

Sincerely,

GENWAL COAL COMPANY



Larry W. Johnson
Engineer



R. Jay Marshall
Chief Engineer

lwj

Enclosures